

L Number	Hits	Search Text	DB	Time stamp
-	0	enright-marybeth".PN.	USPAT; US-PGPUB	2003/08/07 22:27
-	0	enright-marybeth	USPAT; US-PGPUB	2003/08/07 22:29
-	313	steering near column same ignition near switch	USPAT; US-PGPUB	2003/08/07 22:30
-	12	steering near column same mounted same left same ignition near switch	USPAT; US-PGPUB	2003/08/07 22:49
-	12	steering near column same mounted same right same ignition near switch	USPAT; US-PGPUB	2003/08/07 22:31
-	9	(steering near column same mounted same left same ignition near switch) and (steering near column same mounted same right same ignition near switch)	USPAT; US-PGPUB	2003/08/07 22:31
-	3	(steering near column same mounted same right same ignition near switch) not ((steering near column same mounted same left same ignition near switch) and (steering near column same mounted same right same ignition near switch))	USPAT; US-PGPUB	2003/08/07 22:31
-	3	(steering near column same mounted same left same ignition near switch) not ((steering near column same mounted same left same ignition near switch) and (steering near column same mounted same right same ignition near switch))	USPAT; US-PGPUB	2003/08/07 22:31
-	3	((steering near column same mounted same right same ignition near switch) not ((steering near column same mounted same left same ignition near switch) and (steering near column same mounted same right same ignition near switch))) not ((steering near column same mounted same left same ignition near switch) not ((steering near column same mounted same left same ignition near switch) and (steering near column same mounted same right same ignition near switch)))	USPAT; US-PGPUB	2003/08/07 22:31
-	1	steering near column with mounted with left with ignition near switch	USPAT; US-PGPUB	2003/08/25 00:29
-	0	steering near column with mounted with right with ignition near switch	USPAT; US-PGPUB	2003/08/07 22:51
-	6	steering near column with left with ignition near switch	USPAT; US-PGPUB	2003/08/07 22:54
-	4	steering near column with right with ignition near switch	USPAT; US-PGPUB	2003/08/07 22:52
-	0	steering near column with left with right with ignition near switch\$1	USPAT; US-PGPUB	2003/08/07 22:54
-	20	steering near column with ignition near switch and 200/61.54.ccls.	USPAT; US-PGPUB	2003/08/25 00:54
-	1	"3192395".PN.	USPAT	2003/08/25 00:44
-	1	"3145700".PN.	USPAT	2003/08/25 00:45
-	1	"1213811".PN.	USPAT	2003/08/25 00:45
-	1	"1126262".PN.	USPAT	2003/08/25 00:46
-	30	steering near column with ignition near switch and 180/287.ccls.	USPAT; US-PGPUB	2003/08/25 00:52
-	5	"4313520"	USPAT; US-PGPUB	2003/08/25 00:52
-	110	ignition near switch\$2 with (mounted or located) with (panel or dashboard)	USPAT; US-PGPUB	2003/08/25 00:55
-	1	ignition near switches with (mounted or located) with (panel or dashboard)	USPAT; US-PGPUB	2003/08/25 01:06
-	108	ignition near switch with (mounted or located) with (panel or dashboard)	USPAT; US-PGPUB	2003/08/25 01:06
-	17	ignition near switch with (mounted or located) with (panel or dashboard) and 200/\$.ccls.	USPAT; US-PGPUB	2003/08/25 01:07